STAT Cy 6 of 6. 27 Becember 1955 MEMORANDUM POR: HQ. USAY APCSS-PG ATTENTION: Colonel R. A. Berg SUBJECT: STAT Presurement of Items for Project 1. Request the following items be procured for Protect TATS and shipped to STAT Attention: AM/ARG-5LF and VMF Mquipment (complete with tubes) to consist of the following: 1 em R-23/ARC5 Receiver (.19 - .55MC) IF 1 es R-28/AHC-5 Heceiver (THF) 1 ea HT-63/ARC-5 Hask (Two receiver) 1 ea NT-62/ARC-5 NTG Base (Two rec) 1 ca DY-2/ARE-2 Dynamotor (Fernished with VHY Hee) 1 on DY-2A/ARR-2 Dynamotor (Parmished with LF Rec) 1 ca T-23/ARC-5 Transmister (VHF) 1 ee MT-69/ARC-5 Rack (Transmitter) 1 os MT-68/ARC-5 MTG Base (Transmitter) 1 on C-30/ARC-5 Control Unit (VHF Transmitter and VHF Ree Chan **501**) 1 ea MT-80/ARG-5 MTG Plate (G-30) lea C-26/ARC-5 Control Unit (LF Ree) w/(.19-.55mc dial) l es C-42/ARC-5 Control Unit (VHY Rec except chan cel) 1 ea MD-7/ARC-5 Nodulator 1 ea 3T/8/ARC-5 Dynameter (NOD) 1 on MT-76/ARC-5 MTG Base (MOD) 1 ea 37R-1 Anteina (Collins VEF) 2 on MT-4/ARE-2 Ntg Place (C-26) A 2 on (G-42) AN/ARE-14 (VHF OREI and Localiser) to consist of the following: 1 ea R-252A/AHH-14 Receiver or B-54C/ARH-14C 1 es MT-627a/ARH-14 Htg Res) or MT-1162/ARB 1 ea DY-66A/ARM-14 Dynamotor or DY-66B/ARM-14 1 on MT-628/ARE-14 Mtg (Dyn) 1 es C-760/A Control Panel or C-760/B or C-996/A 1 on ID-249A/ARE Course Indicator 1 ea ID-251/ARE Radio Indicator Control 1 em AT-172/ARM-14 Antenna

## 0000603

001081036

```
STAT
```

STAT

STAT

```
Cy _ of 6.
       AM/ARM-18 (Glide Slope): One each of the following are
required:
        1 ea R-322/ARE-18 Receiver
        1 on MY-691/ARK-18 MAG
        1 on 37P-3 Automma (Collins)
        AM/ARE-6 (ADF) Dual to consist of the following:
        2 cm R-101 Prm PBE/ARE-6 Receiver
        2 on MT-274/ARE-6 Mtg (Receiver)
        2 ea ED-200 Control Panel (M.A. Philips Co., Inc.
                         Electronies Div.) or G-758/A
        2 on CU-65/ARN-6 Compling Unit (Aut.)
         2 ea AS-313 Pra PRE/ARE-6 Loop Acey.
        2 on ID-250 Prm PRM/ARM-Indicator
         AN/ARM-12 (Marker) to consist of the following:
         1 on H-122 Prm PRE/ARM-12 Receiver
         1 on MY-589 Pra FRH/ARE-12 Mtg
         1 on 37%-1 Automna (Collins)
         One each of the following are required:
               21154121H Cockpit Sliding Window
               2115410IH Side Sliding Window Seal
               2115410RE Side Sliding Window Seal
               11-364-9-1 Boot Beleer
               5140039-30 Seals
               5140039-32 Seals
               5140039-34 Seals
               5140039-58 Seals
               5140039-60 Seels
               5140039-62 Seals
               5139261-16 Seals
               5139261-18 Seals
               5139261-20 Seale
               5142672-16 Seals
                5142672-42 Seale
          Two cosh of the following are required:
                5115224 Exhaust collector ring assem. complete
                11-364-6-1 Boot delear
                11-364-7-1 Boot deicer
                11-364-8-1 Boot delear
       2. Esqueet these items be procured for delivery so later than
   20 Jaunary 1956.
  WAN the (27 Dec 55)
DYs 5: (bail a) 2[-(Madressee.Cys1,2,3
                                        Colonel, USAF
               cc - In file. Cy 4
                                            0000604
                  - Chrono, Cy 6
```